

U.S. DEPARTMENT OF LABOR WORKPLACE STANDARDS ADMINISTRATION BUREAU OF LABOR STANDARDS

MAY 1971

FORM NO OSHA-20 (MODIFIED)

MATERIAL SAFETY DATA SHEET

MDC CONTROL NO. 1908

			704	a de c	<u> </u>		
	: MAT	ERIAL AND MA	NUFACTURER IDENTIFICATION J				
MANUFACTURER'S NAME	TELEPHONE NO.						
Sherwin Incorporated ADDRESS (NUMBER, STREET, CITY, STATE AND ZIP CO	ODE)		213 261-	0251			
·	•	eles Cal	ifornia 90040				
5007 E. Washington Blvd. Los CHEMICAL NAME AND SYNONYMS	- MIN	eres, car.	TRADE NAME AND SYNONYMS (DMS QF	L 1908)		
N/A			HM-3 Fluorescent Penetrant				
CHEMICAL FAMILY Chemical Compound			FORMULA N/A				
	SECT	ION II: HAZAR	DOUS INGREDIENTS*				
PAINTS, PRESERVATIVES/SOLVENTS	%	TLV (UNITS)	ALLOYS AND METALLIC COATINGS	%	ŢĻŲ (UNITS)		
PIGMENTS	0.5		BASE METAL				
Dyestuff Less than CATALYST	.05	% N /A	ALLOYS				
DATALIST			ALLOTS				
VEHICLE			METALLIC COATINGS				
SOLVENTS	+	-	FILLER METAL PLUS				
Petroleum Solvent 58-6	3 %	200 ppm	COATING OR CORE FLUX				
ADDITIVES Nonionic Surfactant 27-3	2%	N/S	OTHERS				
OTHERS Ethylene Glycol, n-butyl ether 7-	1%	50ppm					
HAZARDOUS MIXTURES OF OTHER LIQUIDS, SOLIDS, OR GASES*							
				_			
	1		THE RESERVE TO SERVE				
		SECTION III: P	HYSICAL DATA				
BOILING POINT (°F) I.B.P.		366 D.F	SPECIFIC GRAVITY (H ₂ O = 1)		.8616		
VAPOR PRESSURE (mm Hg.)		<u> </u>	PERCENT VOLATILE		58-63%		
		1	BY VOLUME (%)		70203/		
VAPOR DENSITY (AIR = 1)		3	EVAPORATION RATE (Ether = 1)	Le	ss than 1		
SOLUBILITY IN WATER		Slight					
APPEARANCE AND ODOR Liquid, Yellow Gr	reen		etroleum Odor				
			XPLOSION HAZARD DATA				
FLASH POINT (METHOD USED)				el	Uel		
150 D.I	F.	T.C.C.		.0	6.0		
EXTINGUISHING MEDIA	Ohan						
FORM, CO ₂ , Dry SPECIAL FIRE FIGHTING PROCEDURES	Chei	nicai					
	unsu	itable, it	spreads the fire				
			·				
UNUSUAL FIRE AND EXPLOSION HAZARDS	one						

*PLEASE DO NOT USE GENERALIZATIONS, SUCH AS PETROLEUM HYDROCARBONS, ALCOHOL, KETONES.

USE SPECIFIC CHEMICAL NAMES, SUCH AS METHANOL, BENZENE, PERCHLOROETHYLENE.

		-	SECT	ION V: HE	ALTH HAZARD DAT	ГА	
THRESHOLD LIMIT VALUE	000						
EFFECTS OF OVEREXPOSE	200 ppm IRE						
Irritatio	n of respira	atory	tract,	centr	al nervous sy	ystem stimulation fol	lowed by
depressio	n of varyin	g degre	ees.				
EMERGENCY AND FIRST AI	D PROCEDURES						
EYES: Wash	with plenty	of wat	ter, S	ee Phy	sician		
SKIN: Remov	e by wiping	, wash	area	with p	elenty of soap	p and water.	
		· · ·	SEC	TION VI:	REACTIVITY DATA		
	UNSTABLE		CONDITIO				· · · · · · · · · · · · · · · · · · ·
STABILITY							
	STABLE	х					
INCOMPATIBILITY (MATER	ALS TO AVOID)						
HAZARDOUS DECOMPOSITI	ON PRODUCTS						
			Ť	Loone	VIII ON TO A VOID		
HAZARDOUS	MAY O	CCUR		CONL	DITIONS TO AVOID		
POLYMERIZATION	WILLN	IOT OCCU	IR .	х			
	L	ALC:		^1	,		
						·····	
STEPS TO BE TAKEN IN CA	SE MATERIAL IS				L OR LEAK PROCE	DURES	
					ged breathing	of vapors, avoid con	itact with
skin and ey	es.						

WASTE DISPOSAL METHOD							
	with absor	bent m	ateria	l or l	nave oil recla	aimer haul away.	
		0507	100 100	ADE OLAL	BRATE ATION IN EA		
RESPIRATORY PROTECTIO	N (SPECIFY TYPE		ION VIII:	SPECIAL	. PROTECTION INFO	DRMATION	
VENTILATION	OCAL EXHAUST	X			<u> </u>	SPECIAL	
	IECHANICAL (GEN				.dha (.	OTHER	
PROTECTIVE GLOVES		Х			EYE PROTECT	FION	
	Yes, rubber	or vi	nyl			Chemical Goggles	
OTHER PROTECTIVE EQUIPMENT OF THE PROTECTIVE EQUIPMENT OF		r or v	invl a	pron			
			-		ECIAL PRECAUTION	IS	
PRECAUTIONS TO BE TAKE			RING			fire hazard.	
						TITC Masaru.	
Keep OTHER PRECAUTIONS	containers	labele	d and	closed	l.		
OTHER PRECAUTIONS	/						
Wali U.W.	naus						
Dale D. Wina:	ns				. 14, 1973 ATE	-	
· · - · · · · · ·				٠.			